

Eskdaleside cum Ugglebarnby Parish Council Asset Register			Previous maintenance	June 2021 review / maintenance	June 2022 review / maintenance	June 2023 review / maintenance
Seat No	Location	Map Ref OS Sheet No 94	Completed works following 2018 survey			
11	LITTLEBECK, ENTRANCE TO FALLING FOSS Memorial seat installed in the memory of Mr Henderson 2007	8791/2 0491/2	Satisfactory	Re-oil (Done March 2022)	1 X Vertical seat back rail broken but remains Satisfactory	1 X Vertical seat back rail broken and 1 x leg showing signs of rot but remains Satisfactory - Contact donator regarding future replacement seat NOTE: UNABLE TO CONTACT DONOR & NO AGREEMENT IN PLACE
15	SANDY LANE, UGGLEBARNBY. Inscribed - In Memory of LtCol Kenneth Allan Oswald SO and of Florance Winifred his Wife of Hempsyke	8863/4 064	Satisfactory	Re-oil (Done March 2022)	Satisfactory	Showing signs of general wear and loose joints but remains Satisfactory - Contract donator regarding future replacement seat. NOTE: NO AGREEMENT IN PLACE
	PARISH NOTICE BOARD (Station) Revarnish/repair/new door 2018	8671/2 0811/4	New Doors 2018. Door repaired 2020. Lock serviced March 2022	Re-oil (Done March 2022)	Satisfactory	Top sign board which is separate to the notice board is rotten - perhaps replace with a plaque
	BRIGGSWATH BUS SHELTER - This Bus Shelter remains the responsibility of the Parish Council - NYCC replaced the glass panels and painted 2004. PC repainted 2018	8691/4 0821/2	Painted by PC 2018. Painted by Skills4Work team 2020	Satisfactory	Satisfactory	Could do with a repaint, last done in 2020 by Skills for Work team
	VILLAGE PUMP - COACH ROAD	861/2 0711/2	Repainted/renovated Mens Sheds 2017	Fence being painted by Skills 4 Work. (Done 2021)	DT to investigate pump cover repairs Summer 2022	DT to investigate pump cover repairs Summer 2023
	WAR MEMORIAL - COACH ROAD	8661/4 0691/2	Fencing and Gate replaced 2019 (Godbolds of Egton.	Satisfactory	Repainting the lettering is still to complete. Metal rails and gate - paint flaking off due to being painted over new galvanising, leave two more years then repaint.	Repainting the lettering is still to complete. Metal rails and gate - paint flaking off due to being painted over new galvanising, leave two more years then repaint.
	VILLAGE SIGN - BRIGGSWATH (2)	Top of Carr Hill Lane		Satisfactory	Starting to show signs of wear, plastic delamination	Starting to show signs of wear, plastic delamination but satisfactory
	VILLAGE SIGN - SLEIGHTS (1)	A169 Blue Bank		Satisfactory	Damaged needs replacing	Damaged needs replacing